

## **M600 OS version 213 update notification**

### **1. Bugs fixing of OS 213:**

- Add PIM (personal information management) backup utility.
- Add SKYPE and SKYPE Receiver switch application (SKYPE can hear from receiver directly)
- Fixed the issue that after align calibration setting sometimes then align point would shift problem.
- Improving data transfer rate when using USB Modem link function
- Fixed when use Bluetooth function for data transferring, M600 would not pop up message to notice if allowing to accept data or not.
- In Speed dial function adds send SMS function (when in frequency dial or index dial press any contact for a while then a message box coming out to ask if dial or send SMS message)
- In phone setting (start/setting/personal/phone) adds skin change function that allows switching dialer skin to Microsoft default or ETEN.
- Fixed call forward problem by re-modified driver of call forward setting.
- Fixed when use Bluetooth headset answer phone call and you get a call waiting and change to the new call the Bluetooth stops working and you need to pick up the phone situation.

### **2. M600 OS 213 update notification:**

#### **Required files:**

ETEN\_M600\_WWE\_R01\_100\_0213.EXE

#### **Normal operation items:**

- Make sure use PC with XP system (better with service pack2) for OS updating.
- Disable all kind of firewall before OS updating.
- Be sure your PC or laptop already installed ActiveSync 4.0 or above version
- Be sure the USB cable is properly connected between PC and Cradle.
- Put M600 on cradle and be sure the ActiveSync is activated with GREEN sign.
- Please backup th all necessary data on PC side before OS updating process.
- Be sure the power adapter is properly connection during the updating process.